

## **International Road Dynamics Inc.**

**Site Service Sheet** 

Clear

| <b>System Type:</b> | ISINC |
|---------------------|-------|
|---------------------|-------|

Date: 10.18.07 State: MN Location: Bemidji - Highway 2

Job #: 10785G Site #: LTPP ID: 270500

## **Loops**

Resistance Resist. to shld. Megger Resist. Inductance Condition Notes

| Lane -   | 1     | Lane - | 2     | Lane - | 3      | Lane - | 4     |
|----------|-------|--------|-------|--------|--------|--------|-------|
| Lead     | Trail | Lead   | Trail | Lead   | Trail  | Lead   | Trail |
| 1.7 ohm  | 1.7   | 1.4    | 1.3   | 1.0    | 1.0    | 0.7    | 0.7   |
| OL       | OL    | OL     | OL    | OL     | OL     | OL     | OL    |
| 1522 M   | OL    | OL     | OL    | OL     | 1257 M | 415 M  | OL    |
| 185.1 uH | 186.0 | 170.5  | 167.3 | 156.8  | 149.0  | 143.5  | 143.4 |
| Good     | Good  | Good   | Good  | Good   | Good   | Good   | Good  |
|          |       |        |       |        |        |        |       |

## **Kistlers**

Resist. to shld. Capacitance Condition Notes

| Lane -  | 1    | Lane - | 2    | Lane - | 3    | Lane - | 4    |
|---------|------|--------|------|--------|------|--------|------|
| OL      | OL   | OL     | OL   | OL     | OL   | OL     | OL   |
| 44.8 nF | 44.7 | 37.0   | 36.6 | 27.8   | 27.5 | 21.9   | 22.0 |
| Good    | Good | Good   | Good | Good   | Good | Good   | Good |
|         |      |        |      |        |      |        |      |

## <u>System</u>

A/C Service
Power Supply
Solar Panel
Back-Up
System Input
Modem Power
Phone off hook
Phone on hook

| OK  |
|-----|
| OK  |
| N/A |
| N/A |
| OK  |
| OK  |
| OK  |
| OK  |
|     |

**Temp Sensor** 

OK

| Technician: | John Folkerts | Date: | 10/18/2007 |
|-------------|---------------|-------|------------|
|             |               |       |            |